



PRO NET™ II

2. MANUFACTURER

PROMA Adhesives Inc.

9801, Parkway, Anjou, Quebec Canada H1J 1P3

Tel.: 514.852.8585

Fax: 514.852.8225

Toll-free: 1 866.51.PROMA (77662)

Email: info@proma.ca

Web: www.proma.ca

3. PRODUCT DESCRIPTION

PRO NET II is a mild acid cleaner designed for grout and ceramic tile maintenance to remove most domestic stains and cement grout haze.

Features

- ♦ Use on ceramic, porcelain, granite, slate and quartz (except marbles and calcareous stones)
- ♦ Use on cementitious, pre-mixed and epoxy grout
- ♦ Use on countertops, floors, walls, showers, shower doors and toilets
- ♦ Organic acid based cleaner
- ♦ Floral scent
- ♦ Non corrosive for skin
- ♦ Safe for chrome and stainless-steel surfaces
- ♦ No phosphates or ammonia
- ♦ Removes calcium residues on car and entrance carpets
- ♦ Removes cement grout haze on tiles after grouting
- ♦ Removes light rust and calcium rings in toilets, bathtubs, shower doors and knobs
- ♦ No VOC
- ♦ For interior and exterior institutional, commercial and residential applications
- ♦ Biodegradable. In conformity with OCDE 301 E rule
- ♦ Meets Ecologic Environment standards for bathroom cleaner
- ♦ Meets Cleaning Performance test ASTM D5343-06-Meets
- ♦ Meets Calcium Carbonate (Hard Water Scale) Solubility Test

Packaging

Ready-to-Use Formula: 700 mL (23.6 oz) bottle [N305-07]

Concentrate: 946 mL (32 oz) bottle [N305-01];

4 L (1.05 US) gal bottle [N305-04]

Limitations

- ♦ Best performance at temperatures between 10°C (50°F) and 35°C (95°F).
- ♦ Do not use on marble, cobblestone, travertine, limestone or other acid etching sensitive material.



4. TECHNICAL DATA

Applicable Standards

For Additional Information, please refer to the most recent TCNA handbook for ceramic tile installation or the TTMAC Specification Guide 09 30 00 Tile Installation Manual, or visit our website at www.proma.ca.

PHYSICAL PROPERTIES (@23° C [73° F] and 50% RH)

VOC content	0 g/100 ml
Color	Light yellow
Odor	Floral scent
Approximate coverage	Varies with the cleaning concentration required and the surface condition.
Shelf life	24 months if kept in its original unopened packaging and stored in a dry location. Protect from freezing.



5. USAGE

PREREQUISITE CONDITIONS

- ♦ Test first on a small and adequate surface, to assess results.

Application and Mixing

Note: Grout must be fully cured at least 28 days old prior to use. Test on a small area to determine ease of application and desired results. Wear gloves and safety glasses when using this product, and protect neighboring areas against unexpected contact with product to avoid possible damage.

Regular Cleaning Showers and Baths

1. Spray ready to use formula directly on the surface and scrub with a white scuff pad.
2. Rinse with clean water.

Regular Cleaning Floors

1. Mix 100 mL (3.4 oz) of concentrated cleaner with 4 L (1.05 US gal) of water.
2. Clean the floor as usual with a mop, a sponge or a nylon scuff pad. Rinse with clean water.
3. For stubborn stains, allow the cleaning solution to work 1 to 2 minutes, scrub and wipe. Increase cleaning solution concentration if needed.
4. If the surface becomes sticky after drying, it is because of the presence of soap residues left on the surface. Rinse the surface with warm to hot water and wipe off.

Deep Cleaning Grout and Tiles

1. Spray or pour undiluted directly on the joints and tiles and let work 1 to 2 minutes.
2. Scrub the joints with a white or black nylon scuff pad or a nylon brush.
3. Rinse thoroughly with clear water.

To Remove Light Efflorescence, Cement Grout Haze, Light Rust Stains and Calcium Deposits

1. Pour undiluted directly on the surface and let work 1 to 2 minutes.
2. Scrub surface with a black or white nylon scuff pad or a hard bristle nylon brush.
3. Rinse with clean water and wipe off.

Application Issues

Efflorescence or Whitish Residue Still Visible on Grout After Cleanup

This problem occurs when the efflorescence phenomenon is confused with a loss of grout color pigmentation, which leaves a grayish appearance on the surface.

Main causes

- ♦ Too much water used in the grout mixture.
- ♦ Excessive water used to remove grout residue on tiles during cleanup.

Corrective measures

- ♦ If efflorescence is still visible after using PRO NET II, try cleaning the grout lines with PRO EFFLONET™ II (see respective data sheet for details). This product has the capacity to etch the surface of the grout lines and remove all minerals that migrated to the surface during the drying period.
- ♦ If a whitish residue is still visible on the grout after cleaning with EFFLONET II, then it is not efflorescence but lack of color pigment in the grout as a result of using too much water during cleanup of the grout residue. Recolor grout using PRO COLOR PREMIUM™ grout colorant to correct this issue (see respective data sheet for details).

Health and Safety

Refer to the Safety Data Sheet (SDS) for complete details.

6. AVAILABILITY AND COST

PROMA products are widely available in Canada and the Northeast United States. To find a distributor of PROMA products, call **toll-free: 1.866.51.PROMA (77662)**.

7. WARRANTY

PROMA warrants that this product is manufactured using quality raw materials and is of merchantable quality and suitable for the purpose for which it was intended. PROMA's liability under this warranty shall be limited to the replacement of its product proven to be defective. Neither seller nor manufacturer shall be liable for any injury, loss or damage, direct or consequential, arising from the use of/or the inability to use this product.

8. MAINTENANCE

Product requires no special maintenance.

9. TECHNICAL SERVICE

For more detailed information on this product, please contact our technical department for proper recommendations and job field assistance. **Toll-free: 1.866.51.PROMA (77662)**.

10. FILING SYSTEM

Additional information is available upon request, or by visiting www.proma.ca.

PROMA Adhesives Inc.

9801, Parkway, Anjou, Quebec Canada H1J 1P3

Tel.: 514.852.8585

Fax: 514.852.8225

Toll-free: 1 866.51.PROMA (77662)

Email: info@proma.ca

© 2025 PROMA Adhesives, Inc.